

ALFA ROMEO

Typ	Motor	Zylinder	Karosserie	Getriebe	Motortyp	Einspritzsystem	Modelljahr	Tanksituation	LPe	R115	Euro-Norm	Bemerkungen
								Lt. Ø platz	typ			
145	1.4i 16V 76kW	4	3DRS.		AR33503	MPI BOSCH	98/00	50 36 BA	4			
							98/00	47 23 VI	4	Boden nicht eben!		
	1.6i 16V 88kW	4	3DRS.		AR67601	MPI BOSCH M1	98/00	50 36 BA	4			
							98/00	47 23 VI	4	Boden nicht eben!		
1.8i 16V 106k	4	3DRS.		AR32201	MPI BOSCH	98/00	50 36 BA	4				
						98/00	47 23 VI	4	Boden nicht eben!			
2.0i 16V 114k	4	3DRS.		AR32301	MPI BOSCH	98/00	50 36 BA	4				
						98/00	47 23 VI	4	Boden nicht eben!			
146	1.4i 16V 76kW	4	5DRS.		AR33503	MPI BOSCH	98/00	50 36 LR	4			
							98/00	47 23 VI	4	Boden nicht eben!		
	1.6i 16V 88kW	4	5DRS.		AR67601	MPI BOSCH M1	98/00	50 36 LR	4			
							98/00	47 23 VI	4	Boden nicht eben!		
1.8i 16V 106k	4	5DRS.		AR32201	MPI BOSCH	98/00	50 36 LR	4				
						98/00	47 23 VI	4	Boden nicht eben!			
2.0i 16V 114k	4	5DRS.		AR32301	MPI BOSCH	98/00	50 36 LR	4				
						98/00	47 23 VI	4	Boden nicht eben!			
147	1.6i 16V 77kW	4	3/5DRS.		AR37203	MPI	00/**	52 25 VI	6.4	X	E 3	Boden nicht eben!
	1.6i 16V 88kW	4	3/5DRS.		AR32104	MPI	00/**	52 25 VI	6.4	X	E 3	Boden nicht eben!
155 TS	1.6i 16V 88kW	4	SEDAN		AR67601	MPI BOSCH	96/97	70 32 BA	4			
	1.8i 16V 103k	4	SEDAN		AR67106	MPI BOSCH	96/97	70 32 BA	4			
	2.0i 16V 110k	4	SEDAN		AR67204	MPI	95/97	70 32 BA	4			
156	1.6i 16V 88kW	4	SEDAN		AR67601	BOSCH M2.10.	98/98	55 36 LL	4			
							98/98	47 23 VI	4	Boden nicht eben!		
	1.6i 16V 88kW	4	SEDAN		AR67601	MPI BOSCH M1	98/00	60 32 BA	4			
							98/00	55 36 LL	4			
							98/00	47 23 VI	4	Boden nicht eben!		
	1.6i 16V 88kW	4	SPORTWAGON		AR67601	MPI BOSCH M1	00/00	55 36 LL	4			
							00/00	47 23 VI	4	Boden nicht eben!		
	1.6i 16V 88kW	4	SEDAN		AR32104	MPI BOSCH ME	00/**	60 32 BA	6.4	X	E 3	
							00/**	55 36 LL	6.4	X	E 3	
							00/**	47 23 VI	6.4	X	E 3	Boden nicht eben!
	1.6i 16V 88kW	4	SPORTWAGON		AR32104	MPI BOSCH ME	00/**	47 23 VI	6.4	X	E 3	
							00/**	55 36 LL	6.4	X	E 3	
	1.8i 16V 106k	4	SEDAN		AR32201	MPI BOSCH	98/00	60 32 BA	4			
98/00							55 36 LL	4				
						98/00	47 23 VI	4			Boden nicht eben!	
1.8i 16V 106k	4	SPORTWAGON		AR32201	MPI BOSCH	00/00	55 36 LL	4				
						00/00	47 23 VI	4				
1.8i 16V 103k	4	SEDAN		AR32205	MPI BOSCH ME	00/**	55 36 LL	7	e	E 3		
						00/**	60 32 BA	7	e	E 3		
						00/**	47 23 VI	7	e	E 3	Boden nicht eben!	
1.8i 16V 103k	4	SPORTWAGON		AR32205	MPI BOSCH ME	00/**	47 23 VI	7	e	E 3		
						00/**	55 36 LL	7	e	E 3		
156	2.0i 16V 114k	4	SEDAN		AR32301	MPI BOSCH	98/00	60 32 BA	4			
							98/00	55 36 LL	4			
							98/00	47 23 VI	4	Boden nicht eben!		
	2.0i 16V 114k	4	SPORTWAGON	MT	AR32301	MPI BOSCH	00/00	55 36 LL	6.4			
						00/00	47 23 VI	6.4				
2.0i 16V 110k	4	SEDAN	MT	AR32310	MPI BOSCH	01/03	55 36 LL	6.4	X	E 3		
						01/03	60 32 BA	6.4	X	E 3		
						01/03	47 23 VI	6.4	X	E 3	Boden nicht eben!	
2.0i 16V 110k	4	SPORTWAGON	MT	AR32310	MPI BOSCH	01/03	47 23 VI	6.4	X	E 3		
						01/03	55 36 LL	6.4	X	E 3		
156 Selespeed	2.0i 16V 114k	4	SEDAN	SP	AR32301	MPI BOSCH	99/00	60 32 BA	6.4			
							99/00	55 36 LL	6.4			
							99/00	47 23 VI	6.4			
	2.0i 16V 114k	4	SPORTWAGON	SP	AR32301	MPI BOSCH	00/00	55 36 LL	6.4			
						00/00	47 23 VI	6.4				
2.0i 16V 110k	4	SEDAN	SP	AR32310	MPI BOSCH	01/03	55 36 LL	6.4	X	E 3		
						01/03	60 32 BA	6.4	X	E 3		
						01/03	47 23 VI	6.4	X	E 3	Boden nicht eben!	
2.0i 16V 110k	4	SPORTWAGON	SP	AR32310	MPI BOSCH	01/03	47 23 VI	6.4	X	E 3		
						01/03	55 36 LL	6.4	X	E 3		
GT	1.8i 16V 103k	4	COUPE		AR32205	MPI BOSCH ME	05/**	55 23 VI	7	X	E 4	Boden nicht eben!
159	1.8i 16V 103k	4	SPORTWAGON	MT	939A4.000	MPI SIEMENS	06/**	55 23 VI	7	X	E 4 *	
							06/**	55 23 VI	7	X	E 4 *	
												Fülltopf hinter Benzinklappe
166	2.0i 16V 114k	4	SEDAN		AR34103	MPI BOSCH M1	98/00	85 36 BA	4			
	2.0i 16V 110k	4	SEDAN		AR36301	MPI	01/03	85 36 BA	6.4	X	E 3	

* Zylinderkopfanpassung Notwendig